

**emenasa**

COGENERATION REFERENCE LIST: FIELD SERVICE

LISTA DE REFERENCIAS COGENERACIÓN: TRABAJOS DE CAMPO

CLIENT	INSTALLATION	COUNTRY	N.º	POWER (kVA)	WORKS
Industrias Roko	Cogen Industrias Roko	Spain	3	1.000	Repair and inspection
Jenbacher	Cogeneration CESPA	Spain	1	1.064	Inspection & bearings replacement
Jenbacher	Murcia Landfill	Spain	1	1.064	Repair and inspection
Jenbacher	Cogeneration Chamusca	Portugal	1	1.068	Inspection & bearings replacement
Jenbacher	Alicante Landfill	Spain	1	1.156	Repair and inspection
Caterpillar Solutions	Sotavento Landfill	Portugal	2	1.200	Inspection
Caterpillar Solutions	Cogeneration Faraday Balaguer	Spain	1	1.200	Commissioning & failure inspection
Jenbacher	Cog Helados Alacant	Spain	1	1.244	Alternator repair
Caterpillar Solutions	Cogeneration Climber	Portugal	1	1.244	Repair and inspection
Caterpillar Solutions	RSU Granollers	Spain	1	1.300	Repair and inspection
Jenbacher	Navarra hospital	Spain	1	1.416	Repair and inspection
Jenbacher	Cogeneration Braval	Portugal	1	1.445	Repair and inspection
Jenbacher / ENC	Cogeneration Cadaval	Portugal	1	1.445	Inspection & bearings replacement
Suldouro	Suldoruro Landfill	Portugal	5	1.445	Repair & winding
Jenbacher	Candigress	Portugal	1	1.445	Repair and inspection
Industrias Roko	Cogeneration Industria Roko	Spain	1	1.445	Repair and inspection
Caterpillar Solutions	Hospital Santarem	Portugal	1	1.445	Repair and inspection
Caterpillar Solutions	Cogeneration Matosinhos	Portugal	2	1.460	Repair and inspection
Caterpillar Solutions	Edar Sur Madrid	Spain	1	1.480	Failure inspection
Jenbacher	Amadoria	Portugal	2	1.500	Inspection & bearings replacement
Jenbacher	Cogeneration Antequera	Spain	1	1.548	Inspection & bearings replacement
Jenbacher	Edar Loyola	Spain	1	1.548	Inspection & bearings replacement
Caterpillar Solutions	Ersuc	Portugal	1	1.745	Alternator repair
Caterpillar Solutions	CRTR Zaragoza	Spain	4	1.750	Inspection and electric testing
Jenbacher	Murcia Landfill	Spain	1	1.750	Repair and inspection
Caterpillar Solutions	Lusotufo	Portugal	1	1.800	Repair and inspection
Caterpillar Solutions	Mabera Cogeneration	Portugal	2	1.800	Repair and inspection
Caterpillar Solutions	Hospital Santo Andreu	Portugal	2	1.850	Alternator inspection and repair
Caterpillar Solutions	Cogeneration Cister	Portugal	1	1.890	Inspection & bearings replacement

CLIENT	INSTALLATION	COUNTRY	N.º	POWER (kVA)	WORKS
Jenbacher	Agrimartin Cogeneration	Spain	1	1.900	Repair and inspection
Jenbacher	Guillema Landfill	Spain	1	1.935	Repair and inspection
Caterpillar Solutions	Campobrick Cogeneration	Spain	4	2.150	Repair and inspection
Caterpillar Solutions	Epicasa Cogeneration	Spain	4	2.150	Alternators inspection and repair
Caterpillar Solutions	Viseu Palacio do Gelo	Portugal	3	2.150	Inspection
Jenbacher	Industrias Jose Aldeia Lagoa	Portugal	1	2.232	Repair and inspection
Caterpillar Solutions	Enerbarroso	Portugal	1	2.300	Repair and inspection
Indar	Edar Galindo	Spain	1	2.300	Alternator inspection and repair
Caterpillar Solutions	Cogeneration La Unión Alhóndiga	Spain	1	2.300	Alternator inspection and repair
Caterpillar Solutions	Sao Bernardo Hospital	Portugal	1	2.300	Alternators inspection
Jenbacher	Cogeneration Muebles IMA	Spain	1	2.325	Repair and commissioning
Cogen Energía	Papelería Brandia Cogeneration	Spain	2	2.480	Inspection
Jenbacher	Industrias Cypsec	Portugal	2	2.560	Repair and inspection
Jenbacher	Sao João Porto Hospital	Portugal	3	3.000	Repair and inspection
Jenbacher	Zoroaga Hospital	Spain	2	3.370	Repair and inspection
Cogen Energía	Hospital Gomez Ulla	Spain	2	3.634	Inspection and electric testing
Jealsa	Boinersa Cogeneration	Spain	7	3.675	Generator inspection and repair
Jenbacher	Sprin Tudela	Spain	3	4.000	Repair and inspection
Veconsa	Veconsa	Spain	2	4.180	Failure inspection
Jenbacher	Carvitin	Portugal	1	4.500	Repair and inspection
Caterpillar Solutions	Cogeneration Fonoz	Spain	4	4.600	Repair and inspection
Caterpillar Solutions	EW Milagros	Spain	3	4.600	Repair and inspection
Sogama	Sogama	Spain	4	4.600	Repair and inspection
Caterpillar Solutions	Fudepor	Spain	4	5.200	Repair and inspection
Indar	Ciclo Combinado Cepalo	Spain	1	5.575	Commissioning
Jenbacher	Formoso do Oeste Cogeneration	Portugal	2	5.800	Repair and inspection
Sampol	Campofrío Burgos	Spain	3	6.183	Generator inspection
Jealsa	Boinersa DSR	Spain	1	7.000	Generator inspection and repair
Caterpillar Solutions	EW Carballo	Spain	3	7.974	Repair and winding
Caterpillar Solutions	EW Villarobledo	Spain	5	7.974	Commissioning
Cogen Energía	DYC Segovia	Spain	1	8.138	Inspection and electric testing
Indar	EDFU	Egypt	1	9.411	Repair and commissioning
Cogen Energía	Papertech	Spain	1	10.600	Electric testing
Indar	Al Jubail ciclo combinado	Saudi Arabia	1	11.250	Repair and inspection
Indar	Linares Ciclo combinado Sacyr	Spain	1	21.000	Commissioning and inspection
Indar	Vernea Clermont Ferrand	France	1	21.500	Generator inspection and testing
Cogen Energía	Sniace Ciclo Combinado	Spain	1	27.500	Inspection